



**Shasta Lake CA 96019**

COURTESY OF

Shasta Premier Inspection Group

Sent: Fri, 24 Jan 2020 15:51

PREPARED BY:

Alex Schmidt

**QUESTIONS?**  
**CLICK HERE TO GET HELP**

## Summary

Carpenter/Handyman	\$3186	<div></div>
Gutters	\$858	<div></div>
Concrete Contractor	\$742	<div></div>
Window	\$519	<div></div>
Roofing	\$485	<div></div>
Painter/DryWall	\$443	<div></div>
Landscaper	\$421	<div></div>
Electrician	\$414	<div></div>
Vents	\$168	<div></div>
Plumber	\$148	<div></div>



## WHOLE HOME ESTIMATE:

**\$6,134**

#	Item	Pg	Action	Projected
<b>CARPENTER/HANDYMAN</b>				
1	Door, sill, framing, and/or trim was observed to be damaged or deteriorated with the presence of wood rot.	15	Change out rotten areas at post and use steel post base.	\$396
2	The fascia was observed to have one or more areas of deteriorated, peeling, or missing paint.	16	Replace damaged areas.	\$742
3	One or areas of the foundation was observed to have high moisture present	21	Leak detection and repair by specialist on noted areas	\$950
4	One or more interior doors were observed be sticky, or dicult to close or latch.	34	Service noted doors .	\$148
5	Evidence of active moisture penetration was observed in one or more areas.	36	Leak detection and repair by specialist on noted areas	\$950
<b>Sub-Total (Carpenter/Handyman)</b>				<b>\$3,186</b>
<b>ELECTRICIAN</b>				
6	One or more electrical receptacle boxes, or other electrical xtire was observed to be loose, or unsecured.	25	Secure outlets noted.	\$121
7	Carbon monoxide detectors were observed to be missing	25	Install carbon monoxide detector.	\$145
8	Stove/oven exhaust hood was observed to be functioning poorly at time of inspection.	40	Service noted items.	\$148
<b>Sub-Total (Electrician)</b>				<b>\$414</b>
<b>PAINTER/DRYWALL</b>				
9	One or more minor cracks were observed in the walls.	37	Patch areas of Sheetrock drywall and paint.	\$443
<b>Sub-Total (Painter/DryWall)</b>				<b>\$443</b>
<b>PLUMBER</b>				
10	Toilet was observed to possibly be leaking at the base.	26	Repair as needed.	\$148
<b>Sub-Total (Plumber)</b>				<b>\$148</b>
<b>ROOFING</b>				
11	Moss growth was observed on the roof covering.	9	Clean off affected areas.	\$223
12	Mastictype sealant was observed on roof, around ashing, storm collars, and/or roof penetrations.	10	Repair as needed to prevent moisture intrusion.	\$262
<b>Sub-Total (Roofing)</b>				<b>\$485</b>

#	Item	Pg	Action	Projected
<b>LANDSCAPER</b>				
13	Grading was observed to be sloping towards the structure	14	Grade low or high areas to improve drainage .	\$421
<b>Sub-Total (Landscaper)</b>				<b>\$421</b>
<b>WINDOW</b>				
14	One or more dualpane windows was observed to have indications of a failed seal.	35	Replace window that has lost thermal seals. Price for one window.	\$519
<b>Sub-Total (Window)</b>				<b>\$519</b>
<b>CONCRETE CONTRACTOR</b>				
15	Damage to cement was observed, that appeared to be caused by settling.	15	Seal with MP1 caulk and monitor.	\$198
16	Cement cracks were observed that are likely from normal concrete shrinkage, or some settling.	17	Install MP1 flexible caulk.	\$247
17	One or more stress or pressure cracks were observed in the concrete slab foundation.	21	Beam patch noted areas.	\$297
<b>Sub-Total (Concrete Contractor)</b>				<b>\$742</b>
<b>GUTTERS</b>				
18	One or more downspouts were observed to terminate discharge or drain too close to the foundation.	10	Install splash blocks and downspout extensions where needed.	\$257
19	Debris was observed to have accumulated in the gutters.	11	Clean out gutters and downspouts, general service and repair.	\$324
20	Rain gutters were observed to be damaged or deteriorated in one or more areas.	11	Repair and secure gutters in noted areas.	\$277
<b>Sub-Total (Gutters)</b>				<b>\$858</b>
<b>VENTS</b>				
21	The exterior dryer vent was observed to terminate too close to the ground.	42	Change vent cover to correct termination and remove build up of lint to improve safety.	\$168
<b>Sub-Total (Vents)</b>				<b>\$168</b>

## Thank you for choosing Repair Pricer

### About Repair Pricer

Repair Pricer is the industry standard for converting inspection reports into accurate repair estimates during the complex home purchasing process, enabling all parties to act quickly and confidently during a critical period. Repair Pricer saves time and reduces stress for everyone when it matters most. To learn more about Repair Pricer, visit [www.repairpricer.com](http://www.repairpricer.com)



It is important you understand that the service provided by RepairPricer.com is purely for estimation and negotiation purposes. We do not guarantee that the prices we estimate for repairs on your report are the same that you will end up paying for that specific repair. Our pricing is based on the average cost for a similar repair in your area, and due to unknown factors or underlying issues that we are not privvy to, actual repair cost may be substantially higher.